

Fig. 1



Fig. 2



Fig. 3

Franking state machine

Project: FM Control



Fig. 4



Processing I_DC_CLOSED is not imperative

○ = Quiet state

Always when the machine goes to Quiet state, it is necessary to let the user know why (Error or R_GO_QUIET).

Set Decades sequence with HV-Limit

Accepting High Value



Fig. 5a

Declining High Value



Fig. 5b

Sending answer too late



Fig. 5c



Fig. 6



Fig. 7a

First time only



Fig. 7b



Fig. 7c



Fig. 7d